PATENT APPLICATION Docket No. 99-C-179D1

CUSTOMER NO. 30430

REMARKS

A post-Notice of Allowance review of this application revealed two errors in the

specification and one error in the drawings. This Rule 312 Amendment is presented to address

and correct those errors. With respect to the specification errors, it was noted that the logic

levels of the signal had been inaccurately/oppositely described. Correction has been made

above. With respect to the drawing error, it was noted that an incorrect voltage reference

notation was used with respect to a ground connection in Figure 2B. Correction is as noted

above and in the attached marked-up drawing sheet. A replacement sheet for Figure 2B with the

correction is also included.

Respectfully submitted,

JENKENS & GILCHRAST,

A Professional Corporation

By:

Andre M. Szuwalski

Registration No. 35,701


1445 Ross Avenue, Suite 3700

Dallas, Texas 75202-2799 Tel: 214/855-4795

Fax: 214/855-4300

IN THE DRAWINGS:

In the lower right-hand corner of Figure 2B, please change the ground reference from "VCCSUB" to "VSS" as indicated in red in the attached proposed drawing correction.



į